COMPLAINT KEPORT

FROM: JANE SIMPSON-PUBLIC INFORMATION OFFICE 864-1011

RECORD NO:

1872

STATUS: ACTIVE

REPORT DATE: 06/16/92 TICKLER DATE: 06/30/92 TYPE OF COMPLAINT: ZONING

COMPLAINANT: Ms. Candice Chandler

ADDRESS: 2554 North Clayton

CITY/STATE/ZIP: Springfield MO 65803

HOME PHONE:

WORK PHONE:

ADDRESS OF PROBLEM: 2500 block of North Patterson

SITUATION: Phone at work is 831-3000, Ext. 350. She is concerned about two lots which are directly behind her on North Patterson. One lot has a semi-trailer parked on it and she is concerned that children may get into the truck and . play. There are also birds flying in and out of it. A privacy fence has been erected on the other lot and she is wanting someone to look at the fence and tell her whether or not it extends the required length; feels it should extend around the corner. She is also concerned about a vehicle parked on this lot marked Brand Horse Battery Company. The vehicle is low to the ground and she is worried that when it rains the battery acid will be washed out onto her property.

DEPARTMENT REFERRAL 1: PUBLIC WORKS DEPARTMENT REFERRAL 2: BLDG REGS

DEPARTMENT REFERRAL 3: HEALTH DEPARTMENT REFERRAL 4: NONE

FOLLOWUP:

Says they already have a drainage problem. PIO routing to Bldg. Regs. to check on fence on the one lot and whether both uses of the lots are zoned properly. Routing to

Public Works to check on drainage problem.

FOR PIO USE ONLY

RESOLVED DATE:

ZONE: 2 Councilman Mac McCartney

ACKNOWLEDGEMENT LETTER SENT: 06/16/92

STATUS LETTER SENT: STATUS LETTER SENT: ABATEMENT LETTER SENT:

City of Springfield Water Pollution Control Section Pollution Complaint/Report Form

Date 6-29-92

Report From: Citizen Fire Dept. Public Information Office Health Department Other
Complainant Information: Name Ms (Andice Chandler Name Toplin Trailer of Springfield The Address 2554 N. Clayton Address 2441 E. Jean (Corner of Patterson Phone Work 831-3000 Ext, 350 Phone 864-8511 Jean) Directions (if needed):
Possible contamination of: soil groundwater surface water what body?
Who_to contact: DNR 417-837-6950
Action needed: Personnel from this office checked this complaint on 6-29-92 At Approximately 11:00 A.M. Brandhorst Battery Vehicle that was referred to in the complaint is an old truck body. It is setting on (supported by) some blocks
(over) ADDRESS

Investigation Results

of wood. We opened the door of the truck sed And
found it to be empty. No further Action appears to
be weeded.
It did appear that someone had backfilled the Area. And that they had placed some of the dirt in a storm water detention basin. This matter was referred to Julie Edwards, Drainage Inspector (Ext. 1939), on 6-29-92 at Approximately 11:50 A.M.
<u> </u>
The second section of the section